



LES COTES TOLERANCEES DOIVENT ETRE CONTROLEES

### COUPE LATERALE



### COUPE DE LONG



PLAN0334-08

Lambris sapin large 2500x185x16.5

FPBOIS

19/12/16